



HKS AVIATION CO., LTD.

2266 kamiide, Fujinomiya-shi,

Shizuoka-ken 418-0103

JAPAN

Tel. +81- 544- 54-1781 Fax. +81- 544- 54-1410

E-mail : hks_aviation@hks-power.co.jp http://www.hks-power.co.jp/hks_aviation/

HKS700E SERVICE LETTER

SL-700-002

Subject:

Recommended next overhauls for first overhauled engine

Engine affected:

HKS700E up to S/N 100600

Recommended next Overhaul:

HKS700E up to S/N 100600 is 500 hrs or from 5 years period of operation.

Next overhaul should be done after 500 hrs or from 5 years period of operation after the first overhaul.

March 2007

HKS AVIATION CO.,LTD